

General Environmental Incident Summary

Incident: 3613 **Date/Time Notice:** 1/19/2015 1014 **DEM Incident No:**
Responsible Party: American Crystal Sugar
Date Incident: 1/18/2015 **Time Incident:** 1815 **Duration:** 15 minutes
County: Pembina **Twp:** 159 **Rng:** 51 **Sec:** 14 **Qtr:**
Lat: 48.59391 **Long:** -97.17112 **Method:** Interpolation from map
Location Description: American Crystal Sugar
8152 County highway 44
Drayton, ND
58225-190
Submitted By: Paul King **Affiliation:** ECS
Address: 8152 County highway 44
City: Drayton **State:** ND **Zip:** 58225

Received By:

Contact Person: Paul King
8152 county Highway 44
Drayton, ND 58225

Distance Nearest Occupied Building: 2 Miles **Release Contained:** Yes

Type of Incident: Tank Overflow

Description of Released Contaminant: Sugar Beet Molasses

Volume Spilled: 500.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Operator failed to accurately monitor tank level.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

None.

Action Taken or Planned:

Molasses production diverted to alternative on-site storage tank. dried beet pulp used to contain and absorb spilled molasses. New level measurement and monitoring instrumentation will be installed on molasses storage tanks to reduce possibility of overfilling.

Wastes Disposal Location: The molasses absorbed dried sugar beet pulp will be provided to producers for livestock feed.

Agencies Involved:

Updates

Date: 1/21/2015 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Washek, Sandi

Updated Volume: 500.00 gallons

Notes:

Tank over filled at ACS. Sent info to Division of Waste Management.